ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura

Street ID	Street Name	Significant Landmark
W0155, W0106, W0153, I0098, W0169, W0329, W0175, W	NA, Lakshmi Sagar Lyt North Side, 1st Crs	Vaishnavi Layout and Surrounding Areas

Segment No.	Total Length (m)
9/C-W0155/S022433	412.06

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	259.63	77.552088	13.077091	77.553534	13.075601	I0469	W0164
2	51.40	77.553366	13.077505	77.553749	13.077231	W0155	W0169
3	101.03	77.553211	13.078066	77.554014	13.077603	W0153	W0169

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to Roads at Vaishnavi Layout and Surrounding Areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahank	3500000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements and Asphalting to Roads at Vaishnavi Layout and Surrounding Areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zoneMODIFIED WORK ORDER	009-16-000008

Work Order No.	Work Order Date	Period of Extention
BBMP/ EE/BTP/WO/124/2016-17	20/09/2016	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
26/09/2016	25/09/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
P VIJAY BABU		0.00

Phone No.	E-Mail ID
9845025446	

Field Inspection Details

Number of Trees	Any Other Information	Name
9		JANARDHAN

Date of Inspection	Remarks
28/01/2017	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0155, W0106, W0153, I0098,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	28/01/2017	27/02/2017	COMPLETED
SE	VASU K M	28/01/2017	27/02/2017	COMPLETED
EE	YARAPPA REDDY	28/01/2017	27/02/2017	COMPLETED
AEE	SHIVAKUMAR	28/01/2017	27/02/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0155, W0106, W0153, I0098,

AE	JANARDHAN	28/01/2017	27/02/2017	COMPLETED
AE	JANARDHAN	28/01/2017	27/02/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0155, W0106, W0153, I0098,